

# IsatPhone 2 Firmware 02.00.01

Briefing note  
25.4.2017

IsatPhone 2 firmware version 02.00.01 has now been released and is available for download. Please follow the link below:

<http://www.inmarsat.com/support/isatphone-2-support/>

Firmware version 02.00.01 supersedes the firmware version 01.12.00 that was released in September 2016.

## Recommendations for installation

This is a **mandatory** firmware upgrade, meaning that the features introduced by the firmware are critical for the functionality of the GSPS service including the network and the IsatPhone 2 handset.

## Pre-requisites for installation and advice after installation

In order to upgrade the handset's firmware you must have a PC running Windows 10, Windows 8, Windows 7, Windows Vista or XP. The **latest version of USB drivers and IsatPhone 2's firmware upgrade tool** must be installed. New USB drivers and a new IsatPhone 2 firmware upgrade tool were released on the 21<sup>st</sup> April 2017.

These can be found on the Inmarsat support website by visiting <http://www.inmarsat.com/support/isatphone-2-support/>

Please read the installation guides for the firmware upgrade tool and USB drivers which are also downloadable from the website.

## Inmarsat.com

Whilst the above information has been prepared by Inmarsat in good faith, and all reasonable efforts have been made to ensure its accuracy, Inmarsat makes no warranty or representation as to the accuracy, completeness or fitness for purpose or use of the information. Inmarsat shall not be liable for any loss or damage of any kind, including indirect or consequential loss, arising from use of the information and all warranties and conditions, whether express or implied by statute, common law or otherwise, are hereby excluded to the extent permitted by English law. INMARSAT is a trademark of the International Mobile Satellite Organisation. Inmarsat LOGO is a trademark of Inmarsat (IP) Company Limited. Both trademarks are licensed to Inmarsat Global Limited. © Inmarsat Global Limited 2017. All rights reserved.

## Installing IsatPhone 2 firmware 02.00.01

To install IsatPhone 2 firmware 02.00.01:

- a. Ensure that USB drivers and the firmware upgrade tool are installed on your PC
- b. Double click on Inmarsat's firmware upgrade tool and follow on screen instructions.

The firmware upgrade will take approximately 7 - 12 minutes. After installation, you can check the firmware version by switching on the phone and selecting **Menu > Settings > About > Firmware version**

## Fixes and enhancements in this release

- Added options for battery charging to extend the battery life
- Added Turkish language support
- Support for new MEAS region
- Improved handling of the leap second event
- Improved reported GPS location accuracy
- Corrected email reply format
- Other improvements and minor bug fixes